(In Buchavan

OFFICE MEMO

November 9, 1976

FROM:

Gary F. Kulibert

SUBJECT:

James Lehrer

On October 27, 1976 at approximately 8:30 a.m., I inspected the Lehrer landfill site with Mr. James Lehrer. As a result of our inspection the following comments were noted. (1) Need better daily covering. (2) He is going to have to address the topsoil requirements for those areas abandoned. (3) The berm could be removed to provide a small earthen berm placed between the site road which runs parallel to the homes. (4) The sludge area south of the new highway still has some areas which need covering. (5) There is an area south of the highway where water is being ponded adjacent to a disposal area. This water will have to be eliminated otherwise it may cause leachate problems. (6) Slope in the disposal area south of the highway are going to have to be stabilized because there is some erosion. (7) All demolition material which is now being disposed by the old incinerator will have to go into the trench area when engineering is completed. This area will then have to be abandoned.

Gary F. Kulibert

GFK:sh